





## **Drag beam failures**



**Stress corrosion crack at  
jack-pad / tiedown pin hole  
(pin missing)**



**Cross section of cracked drag beam  
showing stress corrosion at point  
where pin is located.**